## **Table of Contents**

# **CIP Programming**

Subject	Page
CIP Programming Screens	.3-18
Workshop Exercise - CIP	19

# **CIP** Programming

### Model: All

### **Production: All**



#### After completion of this module you will be able to:

- Retrofit an eject box and perform CIP
- Program a vehicle with complete vehicle coding
- Change the vehicle VO



The opening screen when CIP is started.

CIP		
Termin. CIP Management		
Model series selection:		
E65/E66		
E85		
E83		
E60/E63		
Select the model series of the connected	car.	8

Choose which vehicle you will be programming.



Select depending upon programming required.

To retrofit select Load SW.

To update a vehicle select Vehicle.

Selecting Vehicle will ensure that complete encoding is performed.



Regardless of whether you have selected Load SW or Vehicle, the VO will be determined.



A YES selection will lead you to choose which control module(s) have been replaced.

A NO selection will lead you to Retrofits.



After selecting YES fitted control modules will be determined.

Load software		E60 WBANA73484B057029 -85 km	Terminal 30
Print	Change End		Hardcopy
	Select measures plar	<b>1</b> .	
Date / time:	29.01.2004 / 11:56	State and the second	
Model series:	E60		
Vehicle ID number:	WBANA73484B057029		
Vehicle order:	E60_#0103*NA73%0892&LCSW \$33\$\$354\$403\$415\$416\$423\$43 \$473\$481\$488\$534\$540\$590\$60 \$785\$823\$845\$850\$853\$876\$90	\$205\$217\$226\$229\$302\$319 30\$431\$438\$441\$442\$459 35\$639\$645\$676\$693\$694 39\$991\$992-B110	
Vehicle data status:	E060-03-12-525		
Target data status:	E060-03-12-527		
1. Program DSC (via DIAGBUS)	Old part no. progr. ctrl mod. 6767698	New part no. progr. ctrl mod. 6768616	
	DSC can still be programmed 12 t	times.	
	A CARLED SALES		
8	>	Accept	

After determining the fitted modules, a measures plan will be made. At this point you will be notified if control modules need to be replaced.

Control module replacement is required if the hardware level in a module can not be upgraded to a high enough software level.

In the case above no modules need replacement, in fact on the DSC needs to be reprogrammed.



DSC programming is being carried out.



If you selected no earlier (Have any control modules been replaced?) you would come to this screen.

Here selections to reprogram individual modules can be made or entry into retrofit programming.



Selecting retrofit on the previous screen brings you here.

More selections (such as mobile phone USA) are on the next page, accessed by pressing retrofits on bottom of selection list.

Load software	E60 WBANA73484B057029 –85 km	Termin Termin	
Print Change	End		Hardcopy
			Retrofitting SELECTION
		Î	Retrofits
		-	SRA
			Trailer tow hitch
			Mobile phone US
Retrofits were	added or removed		Through-load facility
			ACC
			CD changer
			Lights package
			Multi-function seats
			Opt. equip.,act. seats

Select the retrofit, in this case the Mobile phone USA.



You will be asked which battery the car has installed.

Load software		<b>E60</b> WBANA73484B057029 –85 km	Terminal 30 Terminal 15
Print Cha	ange End		Hardcopy
			Retrofitting SELECTION
			1 Retrofits
	Select measures plan		1 Mobile phone US
Date / time:	29.01.2004 / 13:59		Added
Model series:	E60		
Vehicle ID number:	WBANA73484B057029		
Vehicle order:	E60_#0103*NA73%0892&LCS \$339\$354\$403\$415\$416\$423\$ \$473\$481\$488\$534\$540\$590\$ \$785\$823\$845\$850\$853\$876\$	W\$205\$217\$226\$229\$302\$319 430\$431\$438\$441\$442\$459 605\$639\$645\$676\$693\$694 909\$991\$992+B110+RASK	
Vehicle data status:	E060-03-12-527		
Target data status:	E060-03-12-527		
1. Program TEL/ULF (via MOST Control)	Old part no. progr. ctrl mod. 6942592	New part no. progr. ctrl mod. 6942592	
2. CCC-BO/M-ASK-BO encoding			
	>	Accept	
Print or copy out the desired	l measures plan.		

A measures plan will be determined and displayed to accomplish the retrofit.

Press Accept.



The retrofit is being carried out.



By selecting Vehicle initially when entering CIP, you will save time when updating the vehicle.

Updating through Load SW differs from Measures Plan determined through Vehicle.

When updating through Load SW only the module programmed is re-coded. You still need to come to this screen and perform Complete Encoding.

By updating through Vehicle, the entire car is automatically encoded, after the programming is complete.

'ehicle	E60 WBANA73484B057029 -85 km	Terminal 30
Print Change	nd	Hardcopy
		Vehicle
		Vehicle order
		Initializations
		Complete encoding
A measures plan has been created and execute this mea	l accepted. It takes 1 minutes to sures plan.	
The measures plan is now carried out w with Cano	ith <i>Start</i> , the process is cancelled <i>cel</i> .	
If cancelled, the entire proce	ess must be repeated!	
	Cancel 3	

Press start to begin the programming and encoding procedure.

## <sup>3</sup> Workshop Exercise - CIP

The purpose of this exercise is to retrofit an eject box to the vehicle and then remove the eject box by changing the VO back to its original state.

The eject box does not have to be physically installed to perform the retrofit... **However** it is recommended that the eject box be installed so that testing may be done after the retrofit procedure.

#### Note: The eject box is already physically installed in the vehicle, and the vehicle has been brought up to the most current programming level.

Enter CIP

When prompted, Select NO... Control Modules have not been installed.

Select Retrofits from bottom right of screen.

Select Retrofits from bottom of selection list.

Select Mobile Phone USA.

A measure plan will be determined, then select Accept.

Select finish.

At this time what modules in the vehicle have been programmed and encoded?

Make a phone call with the mobile phone using the controller.

Did the phone call work? \_\_\_\_

Now disconnect from the vehicle, and cycle the key.

Attempt to use the mobile phone now.

Retrofit the mobile phone again.

Encode the entire vehicle.

Disconnect from the vehicle and make a phone call using the mobile phone.

Why did the phone call work this time?

Hook back up to the vehicle.

Select Vehicle

Select VO

Select Adapt VO

You will be instructed to insert the disc into the DISplus.

When the adaptation is finished the current VO will be displayed.

The mobile phone VO code (K639) should no longer be listed on the VO.